

ZW3D from Entry to Master Tutorial

# 4-5X Machining



**Copyright and Trademarks**

ZWSOFT CO., LTD.(GUANGZHOU). All rights reserved.

## **ZW3D™ V2023 From Entry to Master CAM 4-5X Machining**

This tutorial may be reproduced provided it complies with the terms presented on the LICENSE AGREEMENT supplied.

ZWSOFT CO., LTD.(GUANGZHOU) and the program authors have no liability to the purchaser or any other entity, with respect to any liability, loss, or damage caused, directly or indirectly by this software and training materials, including but not limited to, any interruptions of service, loss of business, anticipatory profits, or consequential damages resulting from the use of or operation of this software.

Updates may be made to this tutorial and incorporated into later editions.

ZW3D™ is a registering trademark of ZWSOFT CO., LTD.(GUANGZHOU)

The ZW3D™ logo is a registering trademark of ZWSOFT CO., LTD.(GUANGZHOU)

ZWCAD™, ZWSOFT™, the ZWCAD™ logo, and the ZWSOFT™ logo are all trademarks of ZWSOFT CO., LTD.(GUANGZHOU)

Printed in the P. R. China.

**ZWSOFT CO., LTD.(GUANGZHOU)**

Room 01-08, 32/F, No.15, Zhujiang West Road,

Tianhe District, Guangzhou 510623, China

(8620)38289780

# Foreword

In this tutorial, we provide various case studies, which are from easy to difficult and combine theory with practice. We hope to improve users' 3D CAD/CAM skills and techniques with ZW3D.

The tutorial bases on our technical engineers' years of experience in the industry and ZW3D, which is the fruit of a lot of efforts and wisdom. We sincerely hope that the tutorial will do help to you, and your precious advice on it is highly welcomed.

There are three series for this tutorial: **Primary Tutorial**, **From Entry to Master Tutorial**, and **Advanced Tutorial**. From easy to difficult, they offer a step-by-step learning process that can meet different user needs.

Primary Tutorial series is for users who have little or no prior 3D CAD/CAM experience. If you are green hands of 3D CAD/CAM software, or if you are a new user of ZW3D, we recommend that you get started with this tutorial. Here you can learn the basic knowledge and concepts of ZW3D, rapidly master the simple operations and workflows of ZW3D, and practice simple cases.

From Entry to Master Tutorial series is for users with basic know-how of 3D CAD/CAM software. If you have experience in 3D CAD/CAM software and want to master common functions of ZW3D, we suggest that you start with this series. Here you can dig deeper into the functions and master more operations of ZW3D.

Advanced Tutorial series is for users with practical experience in 3D CAD/CAM software. If you hope to have a comprehensive command of ZW3D and get the complicated operations done independently, you can choose to learn this series. Here you can learn to use the software more flexibly and get rich experience to increase your efficiency.

What you are learning is **ZW3D From Entry to Master CAM 4-5X Machining**, a master tutorial.

Thanks for being our user!

The ZW3D Team

# Contents

1	4-5X Machining .....	1
1.1	4X Indexing Milling .....	1
1.1.1	Align The Part.....	1
1.1.2	Create Sub Frame.....	2
1.1.3	Create Toolpath Based On Each Frame .....	4
1.1.4	Set Up The Machine.....	9
1.1.5	Set Up Output Space.....	10
1.1.6	Output NC Code:.....	11
1.2	5X Indexing Milling .....	12
1.2.1	Align Part.....	13
1.2.2	Create Sub-Frame For Multiple Faces .....	14
1.2.3	Create Toolpath Based On Different Frame .....	15
1.2.4	Set Up Machine and Output Space.....	15
1.2.5	Output NC Code .....	17
1.3	5X Simultaneous Movement Operations .....	18
1.3.1	5X Plane Cut Operation.....	19
1.3.2	5X Swarf Cut.....	23
1.3.3	5X Drive Curve Cut .....	38
1.3.4	5X Guide Surface ISO Cut .....	42
1.3.5	5X Flow Cut .....	47
1.3.6	5X Side Cut .....	54
2	Summary .....	61






Figure 2 Align the part

### 1.1.2 Create Sub Frame

After enter into CAM let's create the sub frame as follows:

**STEP 01** Create Sub frame for right side

- I. Right click on Frames tab then we can get the Insert Frame command as follows:




Figure 3 Insert frame command

- II. Click on Insert Frame command then the definition form for Frame will pop up as follows

Figure 4 Frame definition form

- III. Then we can click ***create datum*** to create new frame as follows






Figure 8 Finished local frames and default frame

Next we can create toolpath based on these frames.

**1.1.3 Create Toolpath Based On Each Frame**

**STEP 01** Create toolpath on top side: finish the top face based on default frame.

- I. Let's choose 3X Flat Finish operation and choose the whole part as feature as follows. Then choose D10 flat end tool.




Figure 9 Choose part for flat finish

- II. Set up frame for it : open the parameter form to set up which frame to be based on as follows:




Figure 10 Choose default frame

- III. Set up the rest necessary parameters and then calculate the toolpath as follows:




Figure 11 Toolpath for top side



**Notes:** since this process is the same as using 3X milling operation so here we will skip the details for creating the toolpath. And here we just use one operation to show indexing milling, for the rest necessary operations please finish by yourself.

**Tips:** In order to better manage the operations on each side , it is helpful to create operation folder and name it clearly. For example here we can name the folder for the operations in topside as “topside” and put all of the operations into this folder as follows:




Figure 12 Operation folder for top side

**STEP 02** Create toolpath based on Frame 1 on right side as follows:

I. In order to get a clear idea about the toolpath on the left side we can firstly rotate the part as follows:




Figure 13 Rotated part

II. Create a folder and name it as **Right side** and then go to add operations.

III. Pick 3X **Flat Finish** operation. Then Open the parameter form to set up the work frame as follows:




Figure 14 Set up work frame for Flat finish operation

IV. Then set up the Boundaries as follows:








Figure 22 Link tool path for transforming

The link toolpath can clearly show how the tool transform from the default frame to Frame 1, so it is helpful to check if it is safe or not.

IV. Verify the InterPath as follows:




Figure 23 Verify link path

**Notes:** The Interpath operation’s tool should be the same as the tool used by the first operation in next frame as follows:




Figure 24 Tool for InterPath operation

**STEP 04** Create the toolpath on the bottom side as follows:

I. Create toolpath based on the frame 2 as follows:




Figure 25 Tool path on bottom side

II. Insert Interpath operation and set up as follows:




Figure 26 Set up Interpah operation

III. Calculate the Interpath operation we can get the link tool-path between right side and bottom side as follows:




Figure 27 Link path between right side and bottom side

So far we have finished the 4X indexing milling process for this part. Next we need to output the NC code for it. Before we output the NC code, we have to check some necessary setting such as machine type, controller, output space etc.

### 1.1.4 Set Up The Machine

Double click on the machine tab to activate the Machine Manager and set up as follows:




Figure 28 Set up machine

Here let’s choose the **ZW\_FUNAC\_4X\_A** as an example to output.

### 1.1.5 Set Up Output Space

Since here we have already defined different frames,it is necessary for us to specify on which frame to output the NC code.

**STEP 01** Insert a new NC file as follows:




Figure 29 Insert new NC file

**STEP 02** Add operation for output as follows:






Figure 32 Output NC

Output NC code as follows, it shows how the tool rotates around X axis from the default frame to frame1.




Figure 33 Output NC code

If you want to check more, please go through the whole NC code by yourself.

So far, we have finished the sample case for 4X indexing milling. From this process we can find that the key points for the indexing milling are as follows:

- 1) Align the part according to the machine structure
- 2) Create sub frame
- 3) Set up 4&5 X machine type
- 4) Set up the output Space

## 1.2 5X Indexing Milling

Last case we finished the 4X indexing milling. Now we can use the same way to finish the 5X indexing milling case. Following is a 5X indexing milling case we are going to finish:




Figure 34 5X indexing milling case

**Analysis:** From this part we can find that if we want to finish all sides by one clamping, the machine needs to rotate the tool axis around different axis. Here let's suppose the 5X machine is AC type, which means rotating around X, Z. Besides here we just take the finished operation as an example to show how to





Then we can delete or hide the stock.

### 1.2.2 Create Sub-Frame For Multiple Faces

Here we will choose some faces as examples to show this detailed process which is as follows:




Figure 38 Indexing milling area

**STEP 01** Create the first frame as follows:




Figure 39 Create the first sub frame

Finished result is as follows:




Figure 40 Created new frame 1

**Notes :** Here the sub frame is only used to define the tool axis's direction, so the sub frame's origin point can be located at any position. In order to show it clearly, here we chose an obvious position mentioned above.

**STEP 02** Create other frames on area 2 and area 3 as follows:




Figure 41 Finished frame

### 1.2.3 Create Toolpath Based On Different Frame

The process of creating 2X or 3X toolpath based on different frame is the same as 4X indexing milling , so here we will skip this process of creating toolpath and just show you the result as follows:




Figure 42 Finished toolpath

For your reference you can open the file **5X\_indexing\_With\_toolpath.Z3** directly.

But you are strongly recommended to finish it from beginning again by yourself.

### 1.2.4 Set Up Machine and Output Space

**STEP 01** Set up the machine and choose the post processor **ZW\_FUNAC\_5X** :






Figure 46 Set up 5X machine type and rotary axis's limitation



Figure 47 Save modification

**STEP 03** Set up Output space as Machine as follows:




Figure 48 Set up output space

### 1.2.5 Output NC Code

Here just choose the connected operation to output the NC code and check it as follows:

**STEP 01** Choose the connected operation as output:




Figure 49 Choose operations as output

STEP 02 Output NC code and verify




Figure 50 Indexing angle code between default frame and framw1




Figure 51 Indexing angle code between frame 1 and frame 2




Figure 52 Indexing angle code between frame2 and frames3

1.3 5X Silmutaneous Movement Operations

Next we will learn how to use the 5X operations as follows:




Figure 53 5X Simultaneous Movement Operations

Among those operations we have introduced the InterPath Move operation, so we can skip it. As for the **Interactive** operation, since it is not used very often, it will be not introduced in this chapter, if you are interested in it then you can check the help document.

ZW3D CAM 5X simultaneous movement operations integrate both 4X and 5X functions together. Therefore, it is able to switch the 5X simultaneous operation to 4X simultaneous operation by the tool axis control parameter.

**1.3.1 5X Plane Cut Operation**

**Philosophy:** The 5 axis plane cut creates a cutting pattern based on parallel cuts at a user-specified angle with respect to the frames X axis. This cutting pattern can be used to control the tool tip or the contact location of the tool on the part. It is possible to constrain the tool axis to a plane (for 4 axis milling) or to a specific orientation (for 3 axis milling).




Figure 54 5X Plane Cut

**1. How to run 5X plane operation**

5X Plane operation works on general surface, so it only requires that the general part surface can create toolpath. Next Let's open the practice file "**5X Plane Cut.Z3**" as follows:




Figure 55 5X Plane Cut practice part

Then we shall use this part to show you how to create 5X Plane Cut tool path on it:

- I. Define a general surface as follows:




Figure 56 Define general surface for 5X plane cut

II. Calculate operation by default parameter to get toolpath as follows:




Figure 57 5X Plane Cut toolpath

2. Set up 5X Plane Cut parameter:

I. Primary parameters:




Figure 58 Primary parameters

II. Path setting parameters:




Figure 59 Path setting parameters

III. Axis control parameters:






Figure 60 Axis control parameters

- **Fixed Axis:** The tool axis will be determined by lead and roll angles along the cutting direction and relative to the Z axis of the frame. Actually, you can think it is the frame's Z axis, since by default the Lead and Roll angle are all 0. As follows:




Figure 61 Fixed Axis tool.

- **Tip Control:** The local contact data determines the cutter orientation while the cutter tip point is kept within the cutting plane. Actually, when the Tip of Tool is in the cutting plane then the tool axis is the surface's normal way.




Figure 62 Tool tip

- **Contact Control:** The local contact data determines both the cutter orientation and tip point. It uses the local contact point as reference and the normal way of this point together to determine the tool axis's position.










Figure 72 Swarcut primary parameters

For the Basic and Tolerance related parameter actually, every operation is the same meaning. So here let’s skip it. Here are some new parameters we need to explain

- **Cut depth Type:** depth measurement direciton.
- **Z-Level:** means that depth is measured along working frame’s Z axis
- **Along tool:** means that depth is measured along tool axis
- **Max Cut depth:** if we create multiple layers toolpath then this value is the maximum depth for each layer. If we leave it blank then it means only 1 layer toolpath will be created.




Figure 73 Multiple layers swarf cut toolpath along Z level

- **Cutting height :** It is a limitation for depth and only work for **At Top** option as follows




Figure 74 Cutting height of swarf cut

- **Cutting position:** we can regard it as a measurement reference for depth, starting from top or from bottom. If we only create one toolpath then it is used to specify where to cut top or bottom.

- **Side cast offset:** it is used to set up the side thickness of cast part which needs to be removed.
- **Side cut depth:** something like the stepsize in XY.




Figure 75 Side steps

## 2. Path setting parameters




Figure 76 Path setting parameters

- **Path pattern:** set up if use one way or Zigzag pattern
- **Cut order:** This determines the depth cut order. This can be applied to both Base Depths and Side Depths. (Normally used under the condition of side cast offset)
  - **Bottom First:** Cut down to base (part) surfaces first for each side cut.
  - **Side First:** Cut sides first on each level.
- **Fan In:** A distance from a corner seam (edge) at which the tool will begin to lessen the influence of the drive surfaces on the tool axis so that it can assume the optimal orientation on the corner.
- **Fan Out:** A distance the tool may traverse while transitioning from the optimal orientation in a corner to have the tool axis controlled by a drive surface.
- **Cut Overlap:** This is a re-cut distance to obtain smooth part surface when **cutting closed loops**. This distance is added at the end of the cut (retracting the beginning of the cut) at the **cut** feed rate.
- **Cut Direction:** This determines the direction of cut, which are Clime and Conventional.
- **Corner Radius:** Fillet the cut with this radius.

## 3. Axis control parameters:




Figure 77 Axis control parameters

**Axis Option:**

- **Ruled lines:** The tool axis always follows the ruling direction of a drive surface for ruled surfaces, it is used for the ruled drive surface.
- **Vertical:** The tool axis is both tangent to the drive surface and vertically tilted.




Figure 78 Tool axis options

- **Automatic:** The tool axis follows *ruled lines* for curved ruled drive surfaces and will be vertical for other types of drive surfaces including flat ones.

**Real case study**

Next we will use 2 real cases as examples to show how to apply the swarf cut operation to real work.

**1. Case 1: “5X\_Impeller.Z3”**

Let's open the real case “5X\_impeller.Z3” file as follow:




Figure 79 5X\_Impeller file

Then we will create swarf cut toolpath to cut the blade as follow:








Figure 84 Define Axis Control

▼ Lead In		▼ Lead Out	
Lead In Type	Normal	Lead Out Type	Normal
Start Angle In		Start Angle Out	
End Angle In	0	End Angle Out	0
Radius In	0	Radius Out	0
Ramp Length In	1.5	Ramp Length Out	1.5
Ramp Angle In	0	Ramp Angle Out	0

Figure 85 Lead in and lead out

For the rest parameters keep their default setting.

**STEP 03** Calculate toolpath as follows:




Figure 86 Swarf cut toolpath

**STEP 04** Pattern the toolpath by transforming function and setting up the pattern parameters as follows:




Figure 87 Pattern the swarf cut toolpath around Z axis

The finished result is as follows:






Figure 91 cutting required faces

**STEP 01** Heal the highlighted surface Since this file is an imported file and the swarfcut operation has strictly requirements for geometry quality, so it is better to heal the file first before programming. Details are as follows

### I. Delete loops




Figure 92 Delete surface trimmed loops




Figure 93 Delete loops operation 1




Figure 94 Delete loops operation2




Figure 95 Delete loops operation 3




Figure 96 Delete loops operation 4

II. After deleting the loops, we can get the following result:




Figure 97 Result after deleted loops

**STEP 02** Modify surface: Trim the surface to curve as follows:




Figure 98 Trim surface\_right side






Figure 103 Define drive surface

Here we will cut the drive surface to define a drive surface as feature input.

- II. Set up tool size : Use 10 mm flat end mill.
- III. Set up parameter as follows:




Figure 104 Primary parameters




Figure 105 Path setting parameters






Figure 110 Define 4X plane for swarfcut operation

4X Plane option actually is used to force the toolpath to a 4X Tool path. By default the system will automatically create the toolpath according to the surface’s situation. Here the 4X tool path is enough to finish the pocket so even without setting up the Four Axis Plane system can automatically create the 4X toolpath for it. But the end chamfer surface will be different. In order to make a better toolpath here we can modify the part again to the following result:




Figure 111 Simplify hole in end

Next we will go to create toolpath on the chamfer face by the four axis plane option or without it separately.

**STEP 01** Define the chamfer face as drive surface:




Figure 112 Define Define chamfer face as drive surface

**STEP 02** Set up parameters and choose the same tool (D10) as follows:






Figure 113 Primary cutting parameter for cutting chamfer face

**STEP 03** Create toolpath without 4X plane option:




Figure 114 Axis control setting

The toolpath is as follows:




Figure 115 Swarf cut toolpath without 4X plane option

From the result you can find that now actually it is a 5X toolpath not 4X simultaneous toolpath. So it will conflict with your machine. How to solve it? By 4X plane option as follows:

**STEP 04** Set up the 4X plane according to real condition (here let's choose A)




Figure 116 Set up 4X plane



I. Choose the 3D medial command from the wireframe module as follows:




Figure 120 3D Medial command

II. Pick the edges on bottom surface of any tooth socket as input as follows:




Figure 121 Input curves for creating 3D medial curve

After creating the 3D medial curve then enter into CAM let’s create Drive curve cut toolpath.

**STEP 02** Define dirve curve and part surface




Figure 122 Define profile for Drive curve cut




Figure 123 Define part surface

**STEP 03** Customize a taper tool




Figure 124 Customize taper tool

**STEP 04** Set up parameters:

Since most of the parameters are similar to the previous introduced PlaneCut and SwarfCut operations so here we just take some special and different parameter to explain the meaning. For others we just show the setting as follows:

I. Primary parameters:




Figure 125 Primary parameter of 5X Drive Curve

- **Number of Cuts:** means how many cutting layers in depth way.

II. Path setting parameters:




Figure 126 Path setting parameters of 5X Drive Curve

- **Tool side:** includes ON, Left/Right/Center of ball as follows:
  - On: The curve offset defined in any profile feature will be ignored.
  - Left/Right: The cutting tool follows the corresponding left (or right) side of each driving curve when looking down from the z-axis. The left or right offset equals the sum of the curve

offset of the profile feature and the tool radius.

- Center of ball : means the center of ball end mill will locate on the drive curve, it is the same function as the On if tool is not ball end.

III. Axis control parameters:




Figure 127 Axis control parameters of Drive Curve

IV. Link, lead in and lead out parameters:




Figure 128 Link,lead in and lead out parameters of 5X Drive Curve

**STEP 04** Calculate toolpath as follows:




Figure 129 5X Drive Curve toolpath

So far we finished the 5X drive curve toolpath for the tooth socket. But as we can see that we had left some material over, so it is necessary to use another operation to finish the whole tooth socket. Then let's take a look at 5X GuideSurface ISO Cut operation as follows:



II. Enter into the new Auxiliary face part file and create surface as follows:

1) Create a blend curve at one end as follows:




Figure 133 Create a blend curve between 2 edges

2) Then make use of the curve to create a surface by “Bi Rail Loft” command as follows:




Figure 134 Bi Rail Loft




Figure 135 Create Surface by Bi Rail Loft command

3) Then delete the gear shape and just leave the surface alone as follows:




Figure 136 Leave the created surface only

4) Merge the surfaces together as follows:








Figure 140 Define part surface for 5X Guide Surface ISO Cut

**STEP 04** Choose the same tool used in drive curve operation and then set up the parameters as follows:

#### I. Primary parameters:




Figure 141 Primary parameters of 5X IsoCut

- **Stepover:** can choose different type, including Absolute, %Tool Dia, Scallop, Num of Cuts etc. It is the same meaning for the Absolute, %Tool Dia, Scallop, options with what in 3X milling operations.
- **Num of Cuts** means how many toolpath layer you can determine to create, which will fill the whole part face.

#### II. Path setting parameters:






Figure 145 5X Guide Surface ISO Cut toolpath

### 1.3.5 5X Flow Cut

**Philosophy:** The 5 axis Flow Cut operation requires either a 5 axis Swarfcut or a 5 axis Drive Curve Cut as a reference operation that contains two separated cuts. These two cuts will be used as flowing curves. The Swarf cut or Drive Curve Cut can also have multiple depths. ZW3D CAM will select the two bottom cuts as flowing curves. It is very useful for machining areas between two tilted walls (turbine blades for example).

So let's open the file *5X\_Impeller.Z3* again, when introducing the swarf cut operation we have created the swarf cut toolpath to finish the blade as follows:




Figure 146 5X impeller with Swarf cut toolpath

Here we will make use of the part to introduce 5X Flow Cut operation. Now we need to create toolpath for the areas between blades and the out surface of the blade as follows:




Figure 147 Tool path for impeller

Next we will use both introduced swarf cut operation and drive curve operation as reference separately to create the 5X flow toolpath on the desired areas.

#### 1. Reference to Swarf Cut operation

**STEP 01** Create another swarf cut toolpath on the root of blade as follows:




Figure 148 Swarf cut toolpath on root of blade

**STEP 02** Create 5X flow cut reference to the swarf cut as follows:

- I. Define part surface for 5X flow cut as follows:




Figure 149 Define part surface for 5X flow cut

- II. Choose swarf cut as reference operation as follows:




Figure 150 Pick swarfcut2 as reference

- III. Choose Tool : 3 mm Ball End Mill
- IV. Set up parameters




Figure 151 Primary parameters




Figure 152 Path setting parameters

- **Collision check:** choose yes to check if the toolpath will collide with stock
- **Start Point:** it is allowed to set up the start point as follows:




Figure 153 Start point for 5X flow cut




Figure 154 Axis control parameters











After finishing these steps please hide the auxiliary part and then save the file. Next let's take a look at the last operation of 5X, side cut.

### 1.3.6 5X Side Cut

**Philosophy:** The 5 axis Side Cut operation accepts parts or general surface features as geometric inputs. Based upon different axis control options, it allows you to position the cutter in various orientations including normal or side tangent to the part with lead, roll and skew angles. This operation is a good choice for turbine top machining or complex pocket finishing with point control.

First we can take the **5X\_Impeller.Z3** file as an example again to show how to use the side cut operation. Now we need to cut the top region, the final result will be as follows:




Figure 169 5X side cut for the top region of impeller

Next let's create the toolpath step by step as follows:

**STEP 01** Choose 5X Side Cut operation and define the general surface




Figure 170 Define general surface for 5X side cut

Normally a general surface is enough to create the toolpath of 5X side cut.

**STEP 02** Next let's set up the parameters:

#### I. Primary parameters:








Figure 176 Statue\_SideCut case

**STEP 01** Enter into CAM and create 5X Side Cut operation and then add the general surface as follows:




Figure 177 define the statue part as general surface

In order to let the tool stop at the bottom of statue we can define the bottom face as Start check surface as follows:




Figure 178 Define Start Check Surfac

**STEP 02** Set up the parameter according to the above introduction as follows:




Figure 179 Primary parameters for statue cut




Figure 180 Path setting parameters




Figure 181 Axis control parameters

Now let's stop here and calculate the toolpath to check what we will get. Following is the result:




Figure 182 5X Side Cut toolpath for the statue

Next let's make use of the created toolpath to explain axis guide parameters, as follows:




Figure 183 Explanation for axis guide parameters

- **Guide type:** normally use the cylinder, cone, sphere and drive curve. For drive curve we will use another case to show how to use it.
- **Origin:** Can be regarded as the center point of section profile in XY as follows, the picked normal way will pass this origin.




Figure 184 Origin option

- **Normal:** if choose Cylinder, Cone, Sphere etc type, regard it as the center line of the guide geometry which will affect the cutting region together with guide radius.
- **Guide Radius:** It is the section profile's radius of guide geometry which depends on the guide type.
- **Guide Side:** If cut the outside or Pocket.
- **Guide Rule:** if the tool axis guide by guide geometry normal or cutting part's normal.
- **Origin Deflection:** if deflect the origin to allow the tool to engage into the small corner.

Now that most of the parameters are illustrated, let's use another case to explain how to use the drive curve type guide and control point together to do the porting cut.

**2. Porting cut Case:** Open the file **5X PortingCut.Z3** as follows:




Figure 185 5X porting cut case

In this file a drive curve had been created for reference. So in this case we will skip the jobs on how to create the drive curve. Next let's create toolpath for the port shape step by step:

**STEP 01** Define profile for drive curve:




Figure 186 Define drive curve by profile

**STEP 02** Define cutting surface as general surface:




Figure 187 Define general surface

**Note:** it is important to make sure the surface's direction is positive.

**STEP 03** Define a lollipop tool as follows:





